

Toyota Hilux Revo J-deck










Brackets and Rubber Pads.







Torque Wrench Tightening To 18-20 Nm



Torque Wrench Tightening To 14-16 Nm

Note: Over tightening could lead to stressing of structure, leading to potential damage to the canopy. Do not over tighten.





